Work Order ID 1 July-17-13 7:36:46 AM	104705		*104	1705*							Page 1
Item ID: D3137-3 Revision ID: Item Name: GUIDE Start Date: 7/17/13 Required Date: 7/24/13	* Start Qty: 50,00 Req'd Qty: 50.00	*50* *50*		*N900 Cust Item Customer:		100) *	Setup	Start Stop	*N:	S1* S2*
Approvals: Process I QC:	Plan:	Date:	_ 0 -		ate:		1	Run	Start Stop	*NI *NI	R1* R2*
Sequence ID/ Work Center ID	Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Rej Qty		Reject Number	Insp. Stamp
Draw Nbr R	Revision Nbr										
D3137 R	tev F										
*100 *100*	BAND SAW		0.00								
Bandsaw Jeaspa Bandsaw	Memo Cut Blanks.I	Blank size: 1.250" x .750"	0.00 ' x .950" long				at	13-	07-	20	(x 34
	,							•			
*110 **110*	HAAS CNC VERTICAL	MACHINING #1	0.00	DR/4 1	2/22/2	7					
HAAS 1 HAAS CNC vertical machine #1	Memo 1-Machine a	s per Folio FA242 & Dw	0.00 vg D31372-Deburr	7,724 12	,,,,,	-		-			Professional Control
120	QC2- Inspect parts off m	achine FAI/FAIB	0.00	se/St 12	3/07/	, 23.			1.		•
120 QC	Memo		0.00				34	- 4	<u>/</u>		

.

Work Orde		04705		*104	1705*							Page 2
Item ID:	D3137-3 GUIDE			Accept	*N900) <u>04</u> 0	100	n *	Setup	Start Stop	*N	S1*
Item Name: Start Date: Required Date: Reference:	7/17/13	Start Qty: 50.00 Req'd Qty: 50.00	*50* *50*		Cust Item Customer					~ top	^N	S2*
Approvals:	Process F	Plan:	Date:	Tooling:	I	Date:	_		Run	Start	*N	R1*
: :	QC:		Date:	SPC (Y/N):		Date:				Stop	*N	R2*
Sequence ID/ Work Center II	D	Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	t Re Qt		Reject Number	Insp. Stamp
*130		QC8- Inspect parts - secon	nd check	0.00	-DE	13.7.	24	34	,	₽		
QC [Quality Control		Memo		0.00	. ((* 7	∽ /					
1140		Identify as per dwg & Sto	ck Location: 573	5A 0.00								
140 Packaging		Memo		0.00				32/				
Packaging *											B-	7-25
150		QC21- Final Inspection -	Work Order Release	0.00					[:	3h	120	19
150 QC		Memo		0.00				***		<u>/ </u>		7-}

Quality Control

N 1307.26

Page 1

Work Order ID:

104705

Parent Item:

D3137-3

Parent Item Name:

GUIDE

Start Date: 7/17/13

Required Date: 7/24/13

Start Qty: 50.00

Required Qty: 50.00

Comments:

IPP Rev:A02.05.29New IssueNG

IPP Rev:B 08-05-23 revE as per dwg DD verified by:EC

IPP Rev c 08.07.03 ECN1207 EC verified by DD

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
MDELRINB0.75X1.250	,	Purchased	No			100	f	3.8019	0.0791	4.1631579)		

Delrin Bar

Loc	ation_	Loc Qty	Loc Code
MA	T018	3.801912	
	119133	0.008	
	120035	0.001476	
	123027	0.031736	
	m126214	3.7607	

et 13-07-20

x 3.7607

DART AEROSPACE LTD	Work Order:	104 103
Description: Guide	Part Number:	D3137-3
Inspection Dwg: D3137 Rev: F		Page 1 of 1


FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

	L							
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments		
0.175	+/-0.010	.176			BUR OS	6" vern		
Ø0.257	+0.005/-0.000	.257			Pin	GAULE.		
Ø0.65 x 100°	+/-0.030	660			DR 05	6'VERN		
0.425	+/-0.010	,425			DROT	6'VERN		
0.550	+/-0.010	650		,	DR 05	6 VERN.		
1.100	+/-0.010	1./0/			DR 05	6"vero		
0.470	+/-0.010	.470			DROS	6 VEXIN		
0.850	+/-0.010	8<1			DEOS	6" VEREN		
0.143	+/-0.010	1.142			DROS	6" VERN.		
						· ·		
		,						
V								
	.1							

Measured by: DC/SA	Audited by:	PP .	Prototype Approval:	N/A
Date: /3/07/23	Date:	3-7.24	Date:	N/A

Rev	Date	Change	Revised by	Approved
Α	03.11.27	New Issue	KJ/RF	
В	04.11.12	0.175 was 0.145 & Ø0.65 x 100° was Ø0.75 x 100°	KJ/JLM	
С	06.03.15	Dwg Rev updated	KJ/JLM 1.4	
D	08.12.02	Dwg Rev updated	KJ/DD 🚓	78



DRAWN IAJS HAWKESBURY, ONTARIO, CANADA DRAWING NO. CHECKED D3137 MFG. APPR. APPROVED TITLE **BRACKET ASSEMBLY** DE APPR. COPYRIGHT © 2002 BY DART AEROSPACE LTD
IT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITIES FOR MY PURPOSE OR COMPANICATED TO ANY OTHER MERS. DATE 08.05.30

8

NTS

REV. F SHEET 5 OF 5

SCALE

С